



Address Carretera de Murcia, Km 619 30850 Totana Murcia (Spain)

Telephone: +34 968424856 Fax: +34 968424856 Web: www.lariocarrillo.com

Sector: Other construction materials Activity: Exporter, Manufacturer, Marketer Turnover: From 600,000 euros to 1,200,000 euros Employees: From 5 to 9 Brands: LARIO Export Volume: From 30,000 to 60,000 euros Export Countries: France, Germany, USA

## LARIO CARRILLO, S.L.

Tax ID Number: B30249973

Company pottery. The surname Lario, since 1600, stands in Lorca potter. A very long tradition of craftsmanship, transmitted generation, remains in these workshops, is made still-happily-in these disorders, with the usual mud, extracted from the same quarry clay beside the river Sanqunayra, nominating him as Arabs.

#### Contact

Juan Lario . Export Director





#### Products

Sources of clay for gardens Fired-clay floor tiles Código Taric: 690890 TARIC Denomination: Glazed ceramic flags and paving, hearth or wall tiles (excl. of siliceous fossil meals or similar siliceous earths, refractory ceramic goods, tiles made into stands, ornamental articles and tiles specifically ma

Sockets Fired-clay floor tiles Código Taric: 690890 TARIC Denomination: Glazed ceramic flags and paving, hearth or wall tiles (excl. of siliceous fossil meals or similar siliceous earths, refractory ceramic goods, tiles made into stands, ornamental articles and tiles specifically ma



# Spainproducts from Murcia

Instituto de Fomento de la Región de Murcia www.spainproductsfrommurcia.com spainproductsfrommurcia@info.carm.es

### Products

Tiles with borders Fired-clay floor tiles Código Taric: 690890 TARIC Denomination: Glazed ceramic flags and paving, hearth or wall tiles (excl. of siliceous fossil meals or similar siliceous earths, refractory ceramic goods, tiles made into stands, ornamental articles and tiles specifically ma

Hydraulic pavement, no maintenance necesta Concrete paving Código Taric: 680100 TARIC Denomination: Setts, curbstones and flagstones, of natural stone (excl. slate)



The resource of this report item is not reachable.