



SUMINISTROS BEYMA, S.L.

Tax ID Number: B30322911

Suministros Beyma was founded in 1990 and has more that 2,000 m2 of sales and exhibition property in Lorca (Murcia). The firm specializes in the sale of industrial machinery, tools and supplies specifically for the industry, cattle breeding construction and agricultural sectors.

Address Carretera de Granada 61ED Blanco 30800 Lorca Murcia (Spain)

Telephone: +34 968441516 Fax: +34 968470071 Web: www.suministrosbeyma.com Contact

Juan Porlan Blázquez Export Director

Juan Manuel Pelegrín . Export Department

Sector: Equipment for the food industry, Farming technology, Machinery for public works, construction and mining, Other types of equipment and capital assets

Activity: Marketer Turnover: From 1,800,000 to 3,000,000 Employees: From 10 to 19 Brands: BM LANTOL



The resource of this report item is not reachable.

The resource of this report item is not reachable.

Products

4-stroke gasoline engine Launtop LT-160 5.5HP
Motors in general
Código Taric: 85****
TARIC Denomination: Electrical machinery and equipment and parts thereof; sound recorders and reproducers, television image and sound recorders and reproducers, and parts and accessories of such articles

Electric compensers Código Taric: 8501** TARIC Denomination: Electric motors and generators (excl. generating sets)

Generators and generator components Código Taric: 8502** TARIC Denomination: Electric generating sets and rotary converters



Spainproducts from Murcia

Instituto de Fomento de la Región de Murcia www.spainproductsfrommurcia.com spainproductsfrommurcia@info.carm.es

Products

Piston with straps Compensators Launtop by Fiac Motors in general Código Taric: 8502** TARIC Denomination: Electric generating sets and rotary converters

is report Irrigation pumps for farming technology

Industrial machinery in general

Tools and equipment for construction Implements and tools for the construction industry

Equipment for the food industry



The resource of this report item is not reachable.

The resource of this report item is not reachable.



The resource of this report item is not reachable.